Mounting instruction

Passion in high frequency

AIRCELL®5

UHF-Connector, crimp/ Art. No. 7762



1. Cut off cable tail right-angled. Move the crimp-cover over the cable head. Cut off 27 mm of the outer sheath with a knife.



4. Solder the inner conductor and the inner pin at the tip.



2. Bend copper braid backwards. Slit slightly 22 mm of the copper foil and remove it. Then remove 5 mm of the dielectric.



5. Cut off the copper braid with a side cutter and move the crimp jacket to the front.



3. Insert the prepared cable head into the connector housing as far as it will go.



6. Crimp the crimp jacket with a crimp tool; herewith the copper braid will be trapped between the crimp jacket and the connector housing.